



The above images show the area planned for the “entry way” sculpture/seating/garden space. This reflects the current conditions. The site is slightly elevated, and the foundation is primarily dirt.